

---

# Reducing Production Costs

---

Donald J. Wheeler

Fellow American Statistical Association

Fellow American Society for Quality



SPC Press

Knoxville, Tennessee

---

# Contents

About the Author	<i>ix</i>
Acknowledgments	<i>x</i>
Preface	<i>xi</i>

## PART ONE: INTRODUCTION

<b>Chapter 1</b>	<b>The Nature of Data</b>	<b>1</b>
1.1	Cause-and-Effect Relationships	1
1.2	Identifying Control Factors	5
1.3	Assignable Causes and Common Causes	7
1.4	Two Ways to Improve a Process	10
1.5	The Fork in the Road to Process Improvement	12
1.6	Summary	14
<b>Chapter 2</b>	<b>The Analysis of Observational Data</b>	<b>15</b>
2.1	Observational Studies versus Experimental Studies	15
2.2	Process Behavior Charts	17
2.3	Average and Range Charts	20
2.4	The Chart for Individual Values and Moving Ranges	24
2.5	Caution regarding Software	29
2.6	How Process Behavior Charts Work	29
2.7	Using Process Behavior Charts for Continual Improvement	31
<b>Chapter 3</b>	<b>The Opportunities</b>	<b>41</b>
3.1	Performance and Potential	41
3.2	Capability Indexes	45
3.3	Performance Indexes	47
3.4	The Gaps	49
3.5	The Two Definitions of Trouble	50
3.6	The Four Possibilities	52
3.7	Summary	56
<b>Chapter 4</b>	<b>The Costs of Using Conforming Product</b>	<b>57</b>
4.1	The Problem of Production	57
4.2	Tighten the Specifications: The Center Cut Approach	60
4.3	Random Assembly with the Original Specifications	61
4.4	Tweaking the Target Value for the Bearing Diameter	63
4.5	Pre-Sorting the Parts	65
4.6	The Traditional Approaches to Production	66
4.7	The Effects of Reducing Variation at the Source	68
4.8	Summary	73

---

## PART TWO: USING EXCESS COSTS

<b>Chapter 5</b>	<b>From Capabilities to Excess Costs</b>	<b>75</b>
5.1	The Effective Cost of Production and Use	75
5.2	The Gaps between Performance and Potential	80
5.3	The Batch Weight Data	82
5.4	The Methanol Percentages	87
5.5	Tokai Rika Revisited	89
5.6	The Cover Examples	91
5.7	The Tables for Two-Sided Specifications	92
<b>Chapter 6</b>	<b>Economic Operation</b>	<b>93</b>
6.1	The Excess Costs of Production	93
6.2	The Excess Costs of Use	94
6.3	The Effective Cost of Production and Use	95
6.4	The Zone of Economic Operation	98
6.5	The Spurious 1.5 Sigma Shift	99
6.6	Summary	100
<b>Chapter 7</b>	<b>Excess Costs for One-Sided Specifications</b>	<b>101</b>
7.1	One-Sided Safety Specifications	101
7.2	One-Sided Process Specifications	104
7.3	One-Sided Product Specifications	108
7.4	Excess Costs of Use for One-Sided Product Specifications	111
7.5	Using One-Sided Product Specifications	114
7.6	Reassessing the Run-Out Data	114
7.7	The Contamination Data	116
7.8	Summary	119
<b>Chapter 8</b>	<b>Excess Costs for Targets at Boundaries</b>	<b>121</b>
8.1	The Excess Cost Function	121
8.2	Using Tables Nine and Ten	123
8.3	The Run-Out Data	124
8.4	The Contamination Data	126
8.5	Summary	128
<b>Chapter 9</b>	<b>When Nominal Costs Change with Aim</b>	<b>129</b>
9.1	One-Sided Product Specifications without a Target	129
9.2	One-Sided Product Specifications with a Target Value	136
9.3	Target at Boundary	141
9.4	Summary	144
<b>Chapter 10</b>	<b>Excess Costs for Count Data</b>	<b>145</b>
10.1	Specifications and Count Data	145
10.2	Effective Costs of Production for Counts of Items	147
10.3	Effective Costs of Production for Counts of Events	148

---

## PART THREE: TABLES OF EXCESS COSTS

<b>Chapter 11</b>	<b>The Formulas for the Excess Costs</b>	<b>151</b>
11.1	The Structure of the Effective Cost of Production and Use	151
11.2	The Average Costs of Scrap, Rework, and Use	152
11.3	Finding the Effective Cost of Production and Use	157
11.4	One-Sided Process Specifications	159
11.5	The Excess Cost of Production with One-Sided Product Specs	160
11.6	The Excess Cost of Use with One-Sided Product Specs	161
11.7	One-Sided Product Specifications with Targets at Boundaries	162
<b>Tables for Two-Sided Specifications</b>		<b>169-216</b>
Table One	When All Nonconforming Units Are Scrapped	170-176
Table Two	When All Nonconforming Units Are Reworked	178-184
Table Three	When the Average Is on the Scrap Side of the Target Value and the Cost of Rework Is Equal to the Cost of Scrap	186-192
Table Four	When the Average Is on the Scrap Side of the Target Value and the Cost of Rework Is 0.1% the Cost of Scrap	194-200
Table Five	When the Average Is on the Rework Side of the Target Value and the Cost of Rework Is Equal to the Cost of Scrap	202-208
Table Six	When the Average Is on the Rework Side of the Target Value and the Cost of Rework Is 0.1% the Cost of Scrap	210-216
<b>Tables for One-Sided Specifications</b>		<b>218-225</b>
Table Seven	Excess Costs of Scrap and Excess Costs of Use when Nonconforming Product Is Scrapped	218-221
Table Eight	Excess Costs of Rework and Excess Costs of Use when Nonconforming Product Is Reworked	222-225
<b>Tables for One-Sided Specifications with Target at Boundary</b>		<b>226-240</b>
Table Nine	When Nonconforming Product Is Scrapped	226-232
Table Ten	When Nonconforming Product Is Reworked	234-240

---

## APPENDIX

I. Formulas for Measures of Dispersion	243
II. The Coverage of Three-Sigma Limits	244
III. The Transformation of Data	248
Table A.1 Bias Correction Factors for Measures of Dispersion	252
Table A.2 <i>XmR</i> Charts: Charts for Individual Values	254
Table A.3 Average and Range Charts Based on the Average Range	256
Table A.4 Average and Range Charts Based on the Median Range	258
Table A.5 Average and Standard Deviation Charts Based on the Average Standard Deviation Statistic	260
Table A.6 Average and Standard Deviation Charts Based on the Median Standard Deviation Statistic	262
Table A.7 Average and Root Mean Square Deviation Charts Based on the Average Root Mean Square Deviation Statistic	264
Table A.8 Average and Root Mean Square Deviation Charts Based on the Median Root Mean Square Deviation Statistic	266
Table A.9 Normal Theory Values of the Integrals <b>IA</b> , <b>IB</b> , <b>IC</b> , and <b>ID</b>	268
Table A.10 Burr and Normal Values for the Integrals <b>IC</b> and <b>ID</b>	277
Glossary of Symbols	283
Index	287