
EMP III

Evaluating the
Measurement Process
&
Using Imperfect Data

Donald J. Wheeler

Fellow American Statistical Association

Fellow American Society for Quality



SPC Press

Knoxville, Tennessee

Contents

About the Author	<i>xiii</i>
Acknowledgments	<i>xiv</i>
Preface	<i>xv</i>
Preface to the Second Printing	<i>xvi</i>
Chapter 1 Frequently Asked Questions	1
1.1 Questions Regarding Measurements	1
1.2 Four Ways We Use Measurements	3
1.3 A Model for Measurements	5
1.4 Observational Studies versus Experimental Studies	7
1.5 The Organization of This Book	9
PART ONE: CHARACTERIZING THE MEASUREMENT PROCESS	
Chapter 2 Consistency Charts	11
2.1 Two Technicians	11
2.2 An Operational Definition of Measurement Consistency	13
2.3 Which Comes First? The Chart or the Adjustment?	15
2.4 Measurement Consistency for Destructive Tests	18
2.5 Rubber Rulers	19
2.6 Rubber Parts	21
2.7 Consistency Charts for Subjective Values	21
2.8 Summary for Consistency Charts	22
Chapter 3 Precision	23
3.1 Quantifying Precision with the Estimated Standard Deviation	23
3.2 Quantifying Precision with the Probable Error	25
3.3 Manufacturing Specifications	30
3.4 Summary for Consistency Charts	33
Chapter 4 Bias	35
4.1 All Bias is Relative	35
4.2 But Do I Have to Do the Graph?	39
4.3 Consistency of Bias	42
4.4 Comparing Two Procedures for Relative Bias	43
4.5 Summary for Part One: Characterizing a Measurement System	45

PART TWO: EVALUATING THE MEASUREMENT PROCESS

Chapter 5	Relative Utility and Short EMP Studies	47
5.1	The Intraclass Correlation Coefficient	47
5.2	Relative Utility Using Consistency Charts and Product Charts	49
5.3	Four Classes of Process Monitors	52
5.4	A Note on Notation for Measurement Error	54
5.5	Short EMP Studies	55
5.6	Measurement Systems That Use Multiple Determinations	59
5.7	Summary	64
	Worksheet for Short EMP Study	66
Chapter 6	Basic EMP Studies:	
	Identifying Nuisance Components of Measurement Error	67
6.1	Basic EMP Studies and Potential Nuisance Components	67
6.2	Checking for Detectable Bias: Main Effect Charts	73
6.3	Checking for Differences in Test-Retest Error	78
6.4	What to Look For in an EMP Study	84
6.5	Discrimination Ratios and Intraclass Correlation Plots	88
6.6	Summary of Basic EMP Studies	90
Chapter 7	Some Basic EMP Studies	91
7.1	EMP Study Number 33	91
7.2	An EMP Study for Truck Spoke Dimension No. 2	94
7.3	An EMP Study for the Compression Test	96
7.4	An EMP Study for the Nanometric Gauge	101
7.5	The Manual Test Stand for Product T143	103
7.6	A Round-Robin Study for Silica-Producing Volatiles	106
7.7	Summary	112
Chapter 8	Two-Factor EMP Studies	113
8.1	Test Method 623 with Product 1108	113
8.2	Test Method 623 with Product 1108 in a Nested Study	117
8.3	A Nested Study for Test Method 623 with Product 1402	120
8.4	Summary	126

PART THREE: USING IMPERFECT DATA

Chapter 9	Chunky Data or Inadequate Measurement Increments	127
9.1	Chunky Data	127
9.2	Fixing Chunky Data	131
9.3	The Detection Rules for Chunky Data	133
9.4	Will the Standard Deviation Statistic Fix Chunky Data?	136
9.5	Chunky Data in an EMP Study	138
9.6	Summary	138
Chapter 10	Censored Data	139
10.1	Assays for Compound M	139
10.2	Life Testing	146
10.3	Compound Y	147
Chapter 11	Characterizing the Product Not Measured	149
11.1	The Problem of Representation	149
11.2	The Lot Fraction Nonconforming	150
11.3	Acceptance Sampling	152
11.4	Within-Batch Uniformity for Measured Properties	156
11.5	Batch-to-Batch Uniformity and Grand Lots	159
11.6	Quality Assurance with Count Data	161
11.7	Grand Lots versus Acceptance Sampling	162
11.8	Summary	164
Chapter 12	Prediction	165
12.1	The Process Behavior Chart and the Two Voices	165
12.2	What Actions are Appropriate?	167
12.3	Use the Measurements to Adjust the Process?	168
12.4	The Only Reliable Basis for Extrapolation	170

PART FOUR: EXPLANATIONS

Chapter 13	How Many Digits Should You Record?	171
	13.1 How the Measurement Increment Affects the Median Error	171
	13.2 The Uncertainty in the Last Digit	173
	13.3 The Twin Uncertainties Affecting Every Measurement	175
	13.4 Chunky Data and the Measurement Increment	178
	13.5 Summary	179
Chapter 14	The Basis for Manufacturing Specifications	181
	14.1 The Idea Behind Manufacturing Specifications	181
	14.2 Watershed Specifications	182
	14.3 The Bivariate Normal Model	183
	14.4 The Probability of Conforming Product	188
	14.4 Summary	193
Chapter 15	The Usefulness of Measurement Systems	195
	15.1 A Simple Experiment	195
	15.2 Detecting Shifts: How Signals Get Attenuated	201
	15.3 Detecting Shifts: The Theoretical Probabilities	203
	15.4 Attenuation of Signals from the Measurement System	206
	15.5 The Ability to Quantify Process Improvements	208
	15.6 Four Categories of Data for Process Monitoring	210
	15.7 Summary of Relative Utility	215
Chapter 16	Gauge R&R Studies	217
	16.1 A Gauge R&R Study	217
	16.2 The “Percentages” of the Total Variation	219
	16.3 The “Percentages” of the Specified Tolerance	222
	16.4 The Number of Distinct Categories	224
	16.5 The Guidelines	224
	16.6 What Can You Learn From a Gauge R&R Study?	227
	16.7 An Honest Gauge R&R Study	228
	16.8 The Basic EMP Study for the Gasket Thickness Data	232
	16.9 Alternate Estimates of Variance Components	234
	16.10 What Happens Without Any Operator Bias?	235
	16.11 Summary	237

Chapter 17	Concepts and Techniques Used	239
17.1	The Chart for Individual Values and Moving Ranges	239
17.2	The Average and Range Chart	241
17.3	Average and Range Charts with Experimental Studies	243
17.4	Detection Rules for Interpreting Process Behavior Charts	245
17.5	Bias Correction Factors	246
17.6	Degrees of Freedom and the Coefficient of Variation	247
17.7	The Analysis of Means	248
17.8	Interval Estimates Using Student's <i>t</i> -Distribution	250
17.9	For Further Reading	252

APPENDICES

Appendix 1. Glossary of Symbols	254-257
--	----------------

Appendix 2. Bias Correction Factor Tables

Table A.1	Bias Correction Factors	c_2, c_4, d_2, d_3, d_4	258
Table A.2	Using \bar{R} to Estimate Variances	d_2^*	259
Table A.3	Moments for Range Distributions	d_2, d_3, d_4	260
Table A.4	Moments for Distributions of the Standard Deviation	c_4, c_5, c_6	261

Appendix 3. Tables for *XmR* Charts

Table A.5	Degrees of Freedom for the Average Moving Range	262
Table A.6	Degrees of Freedom for the Median Moving Range	263

Appendix 4. Tables for Average and Range Charts

Table A.7	Average and Range Charts based on \bar{R}	A_2, D_3, D_4, E_2	264
Table A.8	Average and Range Charts based on \tilde{R}	A_4, D_5, D_6, E_5	265
Table A.9	Degrees of Freedom for the Average Range		266
Table A.10	Degrees of Freedom for the Median Range		267
Table A.11	Alpha Levels for Average Charts Used in Lieu of ANOM or ANOVA		268
Table A.12	Overall Alpha Levels for Upper Range Limits		269

Appendix 5. Tables for Average and Standard Deviation Charts

Table A.13	Average and Standard Deviation Charts based on \bar{s}	A_3, B_3, B_4, E_3	270
Table A.14	Average and Standard Deviation Charts based on \tilde{s}	A_{10}, B_9, B_{10}, E_6	271
Table A.15	Degrees of Freedom for the Average Standard Deviation Statistic		272
Table A.16	Degrees of Freedom for the Median Standard Deviation Statistic		273

Appendix 6. Tables for Range-Based Analysis of Means

Table A.17	Analysis of Means (ANOM) 5% Critical Values		274
Table A.18	Analysis of Ranges (ANOR) 5% Critical Values		275
Table A.19	Analysis of Main Effect (ANOME) 5% Critical Values		277-279
Table A.20	Analysis of Mean Ranges (ANOMR) 5% Critical Values		280-285

Appendix 7. Miscellaneous Tables

Table A.21	Student's t -Distribution		286
Table A.22	Median Errors in PE Units for Different Measurement Increments		287
Table A.23	99% Interval Estimates for Percent Nonconforming in Lot		288-298
Table A.24	Truncation Effect Scaling Factors $TESF$		299
Table A.25	Process Three-Sigma Multipliers $P3SM$		300

Appendix 8. Worksheets

S	The Short EMP Study		301
H	The Honest Gauge R&R Study		302-304
B	The Basic EMP Study Flowchart		305
B	The Basic EMP Study Worksheet		306-311
	Form for Average and Range Chart or ANOM Chart		312

Index			313-316
--------------	--	--	---------